

NEW SITE IDENTIFICATION

Part A – To Be Completed By Observer			
1.	Person Initiating Report: Jacob Harris	Phone: 526-1877	
	Contractor WAG Manager: Douglas Burns	Phone: 526-4324	
2.	Site Title: 034, Howe Peak Diesel Spill		
3.	Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site. There is a disturbed soil mound near the radio towers on Howe Peak. During the August 1999 site visit, odor was detected on the soil and underside of rocks. The observed debris included cans and small scrap metal. The GPS coordinates of the site are		
	N747265.99 by E253426.16. The reference number for this site is 034 and can be found on the summary map as provided.		
Pa	rt B – To Be Completed By Contractor WAG Manager	<u> </u>	
4.	Recommendation:		
	This site meets the requirements for an inactive waste site, requires investigation, and should be included in the INEEL FFA/CO Action Plan. Proposed Operable Unit assignment is recommended to be included in the FFA/CO. WAG: 10 Operable Unit: 10-08		
	This site DOES NOT meet the requirements for an inactive waste site, DOES NOT require investigation and SHOUL included in the INEEL FFA/CO Action Plan.		
5.	Basis for the recommendation:		
	The conditions that exist at this site indicate the potential for an inactive waste site according to Section 2 of MCP-3448 Reporting or Disturbance of Suspected Inactive Waste Sites.		
	The basis for recommendation must include: (1) source description; (2) exposure concern; and (4) descriptions of interfaces with other programs, as applicable (e.g.	e pathways; (3) potential contaminants of p., D&D, Facility Operations, etc.)	
6.	Contractor WAG Manager Certification: I have examined the proposed site and the believe the information to be true, accurate, and complete. My recommendation is	ne information submitted in this document and s indicated in Section 4 above.	
Na	me: Dander E Burs Signature: Care E 42	Date: 5/25/00	

NEW SITE IDENTIFICATION

Part C – To Be Completed By INEEL FFACO/CO WAG Managers			
7. WAG Operable Unit:			
DOE WAG Manager Concurrence:	Do not concur with the recommendation.		
Signature: Patti troupa			
Date: 5/3/100			
EAR WAG Managers Concurrence:	☐ Do not concur with the recommendation.		
Signature: Reevout			
Date: 6500			
State of Idaho WAG Managers Concurrence: 🔀 Concur with recommendation.	Do not concur with the recommendation.		
Signature: Syssy Winter			
Date: 6-14-00			
Explanation follows:			
Part D - To Be Completed By The INEEL FFA/CO Responsible Program Managers (RPM's)			
8. FFA/CO RPM's Concurrence:			
Name: Kathleen Hain Signature: Zattleen E Hain Date: 72/12/00	⚠ Concur		
	Do not concur. Explanation follows:		
For EPA Region X Name: Wayne Pierre Signature: Management Date: 70 100	Concur		
Name. Wayne Fielde Signature. Printing Cont. Sur.	Do not concur. Explanation follows:		
Name: Dean Nygard Signature Date: 0/28/00	≯ Concur		
Name: Dean Nygard Signature Date: 0/21/00	Do not concur. Explanation follows:		





MISC-34, Howe Peak Diesel Spill



MISC-34, Howe Peak Diesel Spill



MISC 34, Howe Peak Diesel Spill



MISC-34, Howe Peak Diesel Spill



MISC -34, Howe Peak Diesel Spill